



*Beratung - Schadensfallaufklärung - Qualitätssicherung - Forschung - Prüfung*

- Akkreditiertes Prüflabor für Korrosion, Korrosionsschutz und Korrosionsanalytik
  - DAkkS-Registrierungsnummer: D-PL-19138-01-00
  - Institut im Verbund der Technischen Akademie Wuppertal e. V.
  - Institut an der TU Bergakademie Freiberg
- ☎ 0351 871 7100  
Fax 0351 871 7150

Institut für Korrosionsschutz Dresden GmbH • Gostritzer Str. 65 • D-01217 Dresden

## Summary to the test report PB300/106/22

Customer: Brillux GmbH & Co. KG Industrielack  
Otto-Hahn-Straße 14  
59423 Unna

Day of order: 2021-11-04

Test panels (190x105x1 mm) provided by the orderer:

Substrate: steel, hot-dip galvanized  
Surface pretreatment: chromium-free passivation

Coating: 60-80 µm Korro-Protect EP 5816 (Art.-Nr. 5816 – 7100)  
80-100 µm Universal-Polyesterpulver 5940 (Art.-Nr. 5940 – 7016)

The test panels were to be tested in accordance with testing criteria for liquid coating systems on galvanized steel of DIN EN ISO 12944-6, corrosivity category C5 (high).

The following corrosion stresses have been applied:

- Condensation on one side in accordance with DIN EN ISO 6270-1, duration 720 hours
- Salt spray in accordance with DIN EN ISO 9227 (NSS), duration 1440 hours

**The tested coating system fulfils the testing requirements for liquid coating systems on galvanized steel of in accordance with DIN EN ISO 12944-6, corrosivity category C5 (high).**

Institut für Korrosionsschutz Dresden GmbH  
Institut für Korrosionsschutz Dresden GmbH  
Gostritzer Straße 65  
01217 Dresden

i. V. Dr. Andrea Rudolf  
Head of Department Coatings

i. A. Dr. Jörg Hübscher  
Research Associate Coatings

Dresden, 2022-04-28

**The complete results of the examinations are documented in test report PB 300/106/22 by the Institut für Korrosionsschutz Dresden GmbH. This summary is only valid in conjunction with test report PB 300/106/22.**